

SABRE 426

MODEL YEAR 2012 OPTION PRICING Price List #611S426

Issue 8/18/2011

ELECTRICAL	Part #	Revision	
Replace standard batteries with Lifeline AGM	GE0039		1,825.00
Additional AC or DC circuit breaker (specify amperage)	GE0002		113.00
Clarion AM/FM/CD/MP3, satellite-ready stereo receiver with (4) speakers and remote control	GE0013		1,260.00
Prewire for stereo and four speakers	GE0014		378.00
Flat screen LCD TV and DVD player w/TV inlet and outlet	GE0051		2,365.00
Hella Cabin Fan with breaker. Specify cabin	GE0004		235.00
Additional Hella Cabin Fans (each). Specify cabins	GE0005		164.00
Additional 12V outlet (specify location)	GE0003		113.00
Xantrex Battery monitor	GE0034		620.00
NAVIGATIONAL ELECTRONICS			
Grounding system for SSB radio (must be specified prior to molding)	GE0022		2,170.00
ICOM VHF radio M504 w/antenna and flush mount kit	GE0015		1,130.00
Raymarine ST70 Autopilot w/controls on cockpit coaming	GE0052		9,180.00
Offset pedestal guard in lieu of standard	GD0011		148.00
Angled pedestal guard in lieu of standard	GD0043		148.00
MECHANICAL			
Reverse cycle air conditioning 16,000 BTU w/2nd shore cord	GM0014		7,930.00
Additional 7,000 BTU air conditioner	GM0040		5,500.00
4KW gen set installed in sail locker	GE0040		19,257.00
Espar diesel heating system #D5-L	GM0017		9,435.00
FIBERGLASS			
Light Hull color (other than Sabre white)	GH0003		1,265.00
Dark Hull Color	GH0004		3,677.00
Light deck color (other than Sabre white)	GD0001		1,265.00
Contrasting anti-skid color (side deck, coach roof, cockpit)	GD0002		1,581.00
KEEL CHOICES			
Shallow draft bulb/wing keel	GH0024		3,233.00
PLUMBING			
Hot and cold transom shower	GM0006		500.00
Salt water wash down system	GM0010		1,082.00
Fresh water washdown in forward anchor locker	GM0036		250.00
Tank Watch 4 for holding tank	GM0037		435.00
Shorewater inlet to pressure water system	GM0018		210.00
DECK AND EXTERIOR WOOD			
Lewmar V3 windlass w/rope chain gypsy	GD0005		4,202.00
Pre-wire for 12 volt windlass	GD0006		830.00
Cockpit Cushions - Tan. <u>Side seats only</u>	GD0017		On Request
Laid teak cockpit coamings	GD0034		2,530.00
Laid teak on transom step	GD0036		1,010.00
Edson Cockpit table #761 for pedestal guard	GM0003		560.00
Teak bang rail on topsides with stainless steel cap	GD0025		3,950.00
RIGGING			
Navtec hydraulic backstay adjuster, split backstay	GR0010		1,632.00
Selden Rigid Vang led aft	GR0055		720.00
Prep for Inner forestay with running backstays	GR0044		3,170.00
Flag halyard to mast head	GR0030		179.00
Burgee halyard to spreader	GR0031		138.00
SAIL HANDLING			
Furlex roller furling/w deck hardware	GR0056		3,970.00
Prep for furling boom. Delete std boom, vang, reefing lines			POR
Self tacking jib system	GR0039		3,264.00
Harken adjustable genoa car system	GR0041		2,030.00
Additional Lewmar sheet stopper (ea)	GD0007		175.00

Lewmar Electric Lewmar primary winches in lieu of standard	GD0016		11,820.00
Lewmar Electric main halyard winch in lieu of standard	GD0029		5,500.00
Spinnaker gear with Lewmar winches Harken adjustable genoa cars, Navtec Backstay adjuster, Hall Quik Vang and carbon fiber spinnaker pole	GR0013		POR
Aluminum spinnaker pole on mast. 2:1 controls. Lift aft to stopper	GR0053		POR
MPS/Spinnaker halyard led aft to stopper	GR0050		755.00
Second genoa halyard led aft to cockpit w/stopper	GR0018		860.00
Spinnaker pole topping lift led aft to stopper	GR0019		663.00
Cunningham led aft	GR0042		455.00
Spinnaker pole track on mast heel lift	GR0043		1,150.00
DECOR AND INTERIOR WOOD			
Second head unit aft with aft facing chart table			6,120.00
Ultrasuede fabric main salon only	GH0011		2,035.00
Ultraleather fabric (main cabin only)	GH0036		2,035.00
Corian counter in galley (with Corian sink covers)	GH0012		3,050.00
Accord shades on opening and fixed ports	GH0020		888.00

All prices are subject to change without notice and are not contractual

Standard yacht has a Sabre white hull and deck with cherry interior. See individual model specifications and equipment list for complete details. F.O.B. South Casco, Maine.

Sabre sailing yachts are covered by a LIMITED ONE YEAR WARRANTY. This warranty should be thoroughly reviewed by the customer before a purchase agreement is made. Please contact your dealer for details.

Sabre does not guaranty the durability of dark gelcoats. Hulls built with dark colors will fade more quickly than light colors, will show mold imperfections and scratches and can cause the laminate to post cure causing a cosmetic distortion of the surface. These deformations are not structural in nature and therefore are not covered by the Sabre Limited Warranty.